

| INFO'RAPID                         |                                                                                      |
|------------------------------------|--------------------------------------------------------------------------------------|
| C5FU1KQ0 : Version 0 of 13/03/2007 |                                                                                      |
| FOR : C4                           |                                                                                      |
| <b>EFFET CLIENT :</b>              | <b>THE INTERIOR CONTROL FOR ADJUSTING THE HEADLAMP BEAM POSITION NO LONGER WORKS</b> |
| <b>CONDITIONS D'APPARITION :</b>   | <b>WHEN ACTIONING THE INTERIOR CONTROL FOR ADJUSTING THE HEADLAMP BEAM POSITION</b>  |

## ***1. ORIGIN***

The central console ashtray bulb is blown.

## ***2. AFTER-SALES REPAIR***

Replacement of the central console ashtray bulb.

### **2.1. Required component**

1 Bulb (Part No. 6216 C6).

### **2.2. Repair**

Replace:The central console ashtray bulb.

### **2.3. Operation times**

Labour code: 4331 IR10.

Invoicing time: 0,60H.

**N.B. :** No longer complete an incident report (CRI) to report an incident that occurs on a vehicle manufactured before the production solution;On the other hand, send an incident report (CRI) for all cases of recurring problems after application of this information or for all incidents occurring on a vehicle manufactured after the production solution