INFORMATION : FAULT CODE P0409 (ENGINE MANAGEMENT ECU)

DV6C TURBO DIESEL

Engine ECU CONTINENTAL SID 807 branch 2	
Fault code	P0409
After sales description of the fault code	EGR valve : Valve detected jammed closed during the ECU switching to dormant mode phase
Description of the diagnostics	Sticking of the EGR valve in the low position detected by the impossibility of reaching 90 % in 1 second
Conditions of activation of the diagnostics	Just after switching off the engine, without restarting within 1 min
Conditions of disappearance of the fault	Start the engine and let it run for 4 min, then stop the engine and wait for the engine ECU to go into sleep phase for 1 min
Down-grade modes if fault present	-
Switching on of the warning light and/or warning message	-
Main customer complaints likely	Starting problem
	Jerking/stalling
	Lack of power
Suspect areas	EGR valve
	Electrical harness
	Connectors

Copyright Citroen - Provided by C4owners.org