

INFORMATION : FAULT CODE P1445 (ENGINE ECU)*DV6C TURBO DIESEL*

Engine ECU CONTINENTAL SID 807 branch 2	
Fault code	P1445
After sales description of the fault code	Additive adding : The quantity of additive injected into the particulate emission filter has exceeded the maximum threshold The particulate emission filter must be changed
Description of the diagnostics	The volume free in the particle filter is not sufficiently large. Necessary to replace the particle filter at the next service interval
Conditions of activation of the diagnostics	Engine running
Conditions of disappearance of the fault	-
Down-grade modes if fault present	-
Switching on of the warning light and/or warning message	-
Main customer complaints likely	No effects immediately perceptible to the customer
Suspect areas	Particle emission filter at the end of its service life