INFORMATION : FAULT CODE P0336 (ENGINE MANAGEMENT ECU)

DV6C TURBO DIESEL

Engine ECU CONTINENTAL SID 807 branch 2	
Fault code	P0336
After sales description of the fault code	Engine speed measurement : Signal absent when starting
Description of the diagnostics	Absence of signal from the engine speed sensor on starting
Conditions of activation of the diagnostics	Ignition switched on
Conditions of disappearance of the fault	10 successive starts
Down-grade modes if fault present	Irreversible deactivation of the vehicle speed curbing function
	Reversible deactivation of the vehicle speed limiter
	Reversible deactivation of the vehicle cruise control
	Sending of the information "torque uncertain" on the CAN network
	For a gearbox with engine speed regulation (automatic gearbox or piloted manual gearbox), limitation of the torque sent to the gearbox
Switching on of the warning light and/or warning message	-
Main customer complaints likely	Starting problem
	Jerking/stalling
Suspect areas	Engine speed sensor
	Engine speed sensor target
	Electrical harness
	Connectors

Copyright Citroen - provided by CAPriles.org