

INFORMATION : FAULT CODE P1AA0 (ENGINE ECU)

DV6C TURBO DIESEL

Engine ECU CONTINENTAL SID 807 branch 2	
Fault code	P1AA0
After sales description of the fault code	Voltage retaining device : Open circuit or short circuit to earth of the voltage measurement
Description of the diagnostics	Défaut sur la ligne de mesure de tension de l'accumulateur d'énergie (For 480 ms)
Conditions of activation of the diagnostics	Ignition on
Conditions of disappearance of the fault	Ignition on
Down-grade modes if fault present	-
Switching on of the warning light and/or warning message	Warning lamp SERVICE
Main customer complaints likely	Absence of automatic stopping of the internal combustion engine
Suspect areas	Energy accumulator
	Electrical harness