

INFORMATION : FAULT CODE P1351 (ENGINE ECU)

MOUNTING BOSCH AND DIESEL TURBO DV6TED4 WITHOUT FAP OR MOUNTING DELPHI AND DW10BTED4 TURBO DIESEL WITHOUT FAP OR MOUNTING BOSCH AND DIESEL TURBO DV6TED4 90HP FAP OR SIEMENS ASSEMBLY AND DW10BTED4 TURBO DIESEL WITHOUT FAP OR MOUNTING BOSCH AND DIESEL TURBO DV6TED4 FAP OR MOUNTING BOSCH AND DV6ATED4 TURBO DIESEL OR MOUNTING DELPHI AND DIESEL TURBO DW10BTED4 OR SIEMENS ASSEMBLY AND DIESEL TURBO DW10BTED4

MOUNTING BOSCH AND DIESEL TURBO DV6TED4 WITHOUT FAP OR MOUNTING BOSCH AND DIESEL TURBO DV6TED4 90HP FAP OR MOUNTING BOSCH AND DV6ATED4 TURBO DIESEL OR MOUNTING BOSCH AND DIESEL TURBO DV6TED4 FAP

Engine ECU BOSCH EDC16C34	
Fault code	P1351
After sales description of the fault code	Pre-heating relay circuit : Coherence ; Relay supplied and glow plugs not supplied
Description of the diagnostics	The information from the preheating control unit indicates that the relay is open even though the ECU commands the closing of the relay for 2 seconds
Conditions of activation of the diagnostics	Consult the associated contexts for the Pcode forwarding conditions
Conditions of disappearance of the fault	When the ignition is switched on
Down-grade modes if fault present	-
Switching on of the warning light and/or warning message	-
Main customer complaints likely	Lack of power
	Noise
	Jerking/stalling
	Starting problem
Suspect areas	Pre-heater plug
	Electrical harness
	Pre/post heating relay

MOUNTING DELPHI AND DIESEL TURBO DW10BTED4 OR MOUNTING DELPHI AND DW10BTED4 TURBO DIESEL WITHOUT FAP

Engine ECU DELPHI DCM3.4	
Fault code	P1351
After sales description of the fault code	Pre-heating relay circuit : Coherence ; Relay supplied and glow plugs not supplied
Description of the diagnostics	The information from the preheating control unit indicates that the relay is open even though the ECU commands the closing of the relay for 5 seconds
Conditions of activation of the diagnostics	Consult the associated contexts for the Pcode forwarding conditions
Conditions of disappearance of the fault	When the ignition is switched on
Down-grade modes if fault present	-
Switching on of the warning light and/or warning message	-
Main customer complaints likely	Lack of power
	Noise
	Jerking/stalling
	Starting problem
Suspect areas	Pre-heater plug
	Electrical harness
	Pre/post heating relay

SIEMENS ASSEMBLY AND DIESEL TURBO DW10BTED4 OR SIEMENS ASSEMBLY AND DW10BTED4 TURBO DIESEL WITHOUT FAP

Engine ECU SIEMENS SID803	
Fault code	P1351
After sales description of the fault code	Pre-heating relay circuit : Coherence ; Relay supplied and glow plugs not supplied
Description of the diagnostics	The information from the preheating control unit indicates that the relay is open even though the ECU commands the closing of the relay for 5 seconds
Conditions of activation of the diagnostics	Battery voltage less than 15,5 V
Conditions of disappearance of the fault	When the ignition is switched on
Down-grade modes if fault present	-
Switching on of the warning light and/or warning message	-
Main customer complaints likely	Lack of power
	Noise
	Jerking/stalling
	Starting problem
Suspect areas	Pre-heater plug
	Electrical harness
	Pre/post heating relay