INFORMATION : FAULT CODE F994 (ENGINE FUSEBOX)

Engine fusebox	
Fault code	F994
After sales description of the fault code	Air conditioning compressor clutch control fault : Short circuit to positive or ope circuit
Description of the diagnostics	Short circuit to positive or open circuit
Conditions of activation of the diagnostics	Ignition on
Conditions of disappearance of the fault	Return into the value range
Down-grade modes if fault present	-
Switching on of the warning lamp and/or warning message	-
Main customer complaints likely	Malfunction : Production of cold air
	Malfunctioning of temperature regulation
Suspect areas	Earth point (according to engine)
	Clutch harness going towards the earth point (according to engine)
	Clutch harness going towards the engine fusebox 1
	Engine fusebox 1
	air conditioning compressor
	Problem with the engine fusebox 1 output : Air con compressor relay