INFORMATION : FAULT CODE F995 (ENGINE FUSEBOX)

Engine fusebox	
Fault code	F995
After sales description of the fault code	Fault with control of the variable capacity of the aircon compressor : Short circuit to positive or open circuit
Description of the diagnostics	Short circuit to positive or open circuit
Conditions of activation of the diagnostics	Ignition on
Conditions of disappearance of the fault	Return into the value range
Down-grade modes if fault present	-
Switching on of the warning lamp and/or warning message	-
Main customer complaints likely	Malfunctioning of the production of cold air
	Malfunctioning of regulation of the temperature requested
Suspect areas	Earth point (according to engine)
	Valve harness going towards the earth point (according to engine)
	Valve harness going towards the engine fusebox 1
	Engine fusebox 1
	air conditioning compressor
	Problem with the engine fusebox 1 output : Transistor for controlling the aircon compressor capacity